



Underwriters Laboratories

UNDERWRITERS LABORATORIES INC .
INSPECTION REPORT - Type L Service
E34503411103141317

Date	03/14/2011	File Number	E345034
Responsible Office	Toronto	Volume	1
Inspection Center	287	Account / Order Number	0764 - 1
CCN	ZPFW2	UL Rep Name	Rene Habermann
Product Category	Wiring Harnesses - Component	UL Representative ID	29752
Subscriber - Factory Number	100560-382	Factory Representative	Mr. Andreas Arnold
Manufacturer Name	DISTRONA GMBH	Factory Rep Phone	+49-6655-9870-330
Manufacturer Address	AM KAUTZGRUND 18	Factory Rep Email	arnold@distrona.de
	FLIEDEN		
	36103 GERMANY		

Nature of Visit	Initial Production Inspection	Sample Status	Samples not required
Listing/Classification/Recognized (Unlisted) Component Marks Used Since Last Visit	No	Listing/Classification/Recognized (Unlisted) Component Marks Removed	No
Variation Notice Issued	No		

VN Corrective Action Follow-up Performed? No

PRODUCT DOCUMENTS / PRODUCTION READY VISIT

☒ No Products Examined - Production Ready Visit

Authorization to use the UL Mark is contingent upon a regular countercheck of the products intended to be UL Labeled to ensure compliance to UL requirements. Since there was no completed UL Labeled production at the time of this inspection, **please notify your UL Field Representative (named on this report) as soon as the next production date or dates are known, so that a UL inspection can be conducted prior to the next shipment of UL Marked product.**

SAMPLE DOCUMENTS

If samples are required to be sent to ULI Laboratory, indicate below. If required samples are not sent, explain in the Comments area.

Type/Style/ Cat/Model	Name	Sample Tag Number	Shipped to Office
--------------------------	------	-------------------	-------------------

No Samples

Additional Comments: IPI done. Lables not orderd yet. Mr. Arnold will order Lables at the Lable Center.

In addition to the requirements specified in the applicable UL Services agreement and Follow-Up Service Procedure, UL further defines responsibilities, duties and requirements for both manufacturers and UL representatives in the document titled, "UL Mark Surveillance Requirements" that can be located at the following web-site: www.ul.com/fus. Manufacturers without Internet access may obtain the current version of this document from their local UL customer service representative or UL field representative.